GOSFORD CITY COUNCIL

KARIONG AREA Drainage Investigation





Prepared by Stormwater & Drainage Group AWT ENGINEERING

Final Report January 2003

Verification Sheet

Prepared by:	Ivan Tye & Freda Leong			
N / . · · · · · · ·	. –			
Verified by:	Ivan I ye			

KARIONG AREA

Drainage Investigation

1	SUMMARY	5
2	INTRODUCTION	7
	2.1 OBJECTIVES	7
	2.2 STUDY AREA	7
3	DATA COLLECTION	8
	3.1 CONTOURS	8
	3.2 CADASTRAL DATA	8
	3.3 COUNCIL'S DRAINAGE DATA	8
	3.4 GROUND SURVEY	8
	3.5 RAINFALL DATA	8
	3.6 RESIDENT QUESTIONNAIRES	9
-	3.7 CLOSED CIRCUIT TELEVISION (CCTV)	9
4	HYDROLOGIC AND HYDRAULIC MODELLING	10
	4.1 GENERAL	10
		10
		11
	4.4 TTDRAULICS	11
	4.4.1 Outlet Water Level	12
	4.4.3 Retarding Basins	12
	4 4 4 Sag Points	12
	4.4.5 Existing System Performance	12
	4.4.6 Arunta Avenue Catchment	13
	4.4.7 Belsham Road Catchment	13
	4.4.8 Casey Crescent Catchment	14
	4.4.9 Truscott Avenue Catchment	14
5	RESIDENT QUESTIONNAIRES	16
6	CLOSED CIRCUIT TELEVISION (CCTV)	17
7	DRAINAGE MANAGEMENT STUDY	18
	7.1 ARUNTA AVENUE CATCHMENT	18
	7.1.1 Old Mount Penang Road Sub-Catchment	19
	7.2 BELSHAM ROAD CATCHMENT	19
	7.3 CASEY CRESCENT CATCHMENT	19
	7.4 TRUSCOTT AVENUE CATCHMENT	20
8	WATER QUALITY	21
	8.1 GENERAL	21
	8.2 WATER QUALITY RECOMMENDATIONS	22
9	WATER SENSITIVE URBAN DESIGN	23
10	COSTING OF WORKS	25
11	DRAINAGE MANAGEMENT PLAN	26
12	REFERENCES	27
13	GLOSSARY OF TERMS	28

FIGURES

Figure 1	Locality Map
Figure 2	Site Plan
Figure 3a	EXISTING DRAINAGE, Arunta Avenue Catchment
Figure 3b	EXISTING DRAINAGE, Belsham Road Catchment
Figure 3c	EXISTING DRAINAGE, Casey Crescent Catchment
Figure 3d	EXISTING DRAINAGE, Truscott Avenue Catchment
Figure 4a	DRAINS MODEL LAYOUT – Arunta Avenue Catchment
Figure 4b	DRAINS MODEL LAYOUT, Belsham Road Catchment
Figure 4c	DRAINS MODEL LAYOUT, Casey Crescent Catchment
Figure 4d	DRAINS MODEL LAYOUT, Truscott Avenue Catchment
Figure 5a	EXISTING DRAINAGE SYSTEM PERFORMANCE, Arunta Avenue Catchment
Figure 5b	EXISTING DRAINAGE SYSTEM PERFORMANCE, Belsham Road Catchment
Figure 5c	EXISTING DRAINAGE SYSTEM PERFORMANCE, Casey Crescent Catchment
Figure 5d	EXISTING DRAINAGE SYSTEM PERFORMANCE, Truscott Avenue Catchment
Figure 6a	CCTV COVERAGE – Sheet 1 of 2,
Figure 6b	CCTV COVERAGE – Sheet 2 of 2,
Figure 7	RESIDENT INTERVIEW RESPONSES
Figure 8	DRAINAGE MANAGEMENT PLAN

TABLES

Table 1	Design Rainfall Intensities
-	

- Table 2 DRAINS Model Parameters
- Table 3 DRAINS Model Results Arunta Avenue Catchment
- Table 4 DRAINS Model Results –Belsham Road Catchment
- Table 5
 DRAINS Model Results –Casey Crescent Catchment
- Table 6
 DRAINS Model Results Truscott Avenue Catchment
- Table 7
 Council's Drainage Standards
- Table 8
 Typical Pollutant Loads in Urban Stormwater
- Table 9 Cost of Works
- Table 10 Proposed Drainage Works

APPENDICES

- APPENDIX A DRAINS Model Input Data (Provided in a separate cover)
- APPENDIX B DRAINS Model Results (Provided in a separate cover)
- APPENDIX C Summary of CCTV results
- APPENDIX D COSTING OF WORKS

FOREWORD

The State Government's Flood Policy is directed at providing solutions to existing flooding problems in developed areas and to ensuring that new development is compatible with the flood hazard and does not create additional flooding problems in other areas.

Under the Policy, the management of flood liable land remains the responsibility of the local government. The State Government subsidises flood mitigation works to alleviate existing flood problems and provides specialist technical advise to assist Councils in the discharge of their floodplain management responsibilities.

The Policy provides for technical and financial support by the Government through the following four sequential stages:

- Flood Study Determines the nature and extent of the flood problem.
- Floodplain Management Study Evaluates management options for the catchment in respect of both existing and proposed development.
- 3. Floodplain Management Plan Involves formal adoption by Council of a plan of management for the catchment.
- Implementation of the Plan Construction of flood mitigation works to protect existing development and use of Local Environmental Plans to ensure new development is compatible with the flood hazard.

The Kariong Drainage Investigation constitutes the first three stages of the management process for this catchment. AWT Engineering Pty Ltd has prepared this study for Gosford City Council.

1 SUMMARY

In July 2000, Gosford City Council undertook investigation of the following:

- the extent of stormwater flooding associated with Council owned infrastructure;
- the extent of structural defects in the stormwater system; and
- the development of a Drainage Management Plan which outlines works required to mitigate the risk of flooding and to repair structurally defective infrastructure in the Kariong Catchment.

Kariong is located approximately five kilometres west of the Gosford Central Business District. The catchment is bounded by the Pacific Highway to the north and Brisbane Water National Park to the east, south and west. The majority of the catchment drains to Mooney Mooney Creek, which is a tributary of the Hawkesbury River.

This report comprises three main investigation stages, namely:

- 1. Drainage Study, which identifies:
 - the causes and extent of the existing drainage problems by estimating the catchment runoff and then assessing the flow capacity of the existing drainage system,
 - the extent of structural defects of the drainage infrastructure,
- 2. Drainage Management Study, which identifies:
 - various drainage strategies or mitigation works to address the existing flooding problems,
- 3. Drainage Management Plan, which defines:
 - recommended plan of works best suited to resolve the flooding problems.

In Stage 1, the Drainage Study, a hydrologic/hydraulic computer model was established for the catchment. The model was used to determine the following:

- 5 year, 10 year, 20 year and 100 year ARI design peak flows;
- flow contained in the existing pipe system; and
- overland flow in terms of quantity, velocity and depth.

It was found that, in general, the existing drainage system met the Council's standard for pipe drainage. Where the pipe system was determined to be below Council's standard, the excess flow was tested against safe overland flow depth and velocity. It was determined that for the 100 year ARI storm event, overland flows in the lower reaches of the catchment generally exceeded what is considered to be a safe flow depth times velocity multiple

The mitigation works considered in this study included:

- pipe and culvert amplification;
- extension of drainage lines;
- additional stormwater pits; and
- new drainage lines.

The standard of flood protection to be afforded to the area was based on Council's latest specification for the design of stormwater drainage works and the specification for pedestrian and vehicle safety in overland flow paths.

Stage 1 of the study included the inspection of all pipes equal to and greater than 900 mm diameter with the aid of Closed Circuit Television (CCTV).

The CCTV inspections detected significant defects including the following:

- open joints (greater than the pipe wall thickness);
- leaking joints;
- direct break ins with small diameter pipes and poor sealing of joints;
- intrusion of small pipes by more than 100 mm into the larger pipe and causing loss of hydraulic capacity;
- cracked pipes, both circumferential and longitudinal; and
- tree root invasion via open pipe joints.

Individual components of works have been costed and given an order of priority to assist Council in preparing a Works Program for the area. The construction works have been estimated to cost approximately \$1.1M.

An "Exhibition Draft" report was prepared in October 2001 and was advertised during December 2001 and January 2002 for public review and comment. The comments received from the public led to the inclusion of additional drainage works recommended for construction. The cost of construction works was re-estimated and determined to cost approximately \$1.2M.

2 INTRODUCTION

2.1 OBJECTIVES

The objectives of this report are set out below:

Stage 1 – Drainage Study:

- Identify the nature and extent of the existing drainage problems by:
 - ~ assessing the flood history of the catchment;
 - ~ estimating catchment runoff;
 - ~ assessing the capacity of the existing drainage system;
 - ~ determining overland flow paths and areas of ponding;
 - ~ determine faulty/damaged sections of underground conduits;
 - ~ determine areas of erosion and sedimentation;
 - ~ determine likely sources of gross pollutants; and
 - ~ determine likely sources of nutrients.

Stage 2 – Drainage Management Study:

- Identify various drainage strategies or mitigation works to address the existing flooding problems within the catchment.
- Identify strategies to fix faulty/damaged sections of underground conduits.
- Identify drainage strategies to mitigate erosion and sedimentation.
- Identify works to trap gross pollutants and nutrients.

Stage 3 – Drainage Management Plan:

- Identify the optimal scheme of works and/or measures which best meet Council's aims and objectives of minimising the extent of the flooding problem to an acceptable standard (houses to be flood free in a 100 year ARI event).
- Identify the optimal method of underground conduit repair.
- Identify the optimal works and measures to prevent erosion, sedimentation.
- Identify the optimal works and measures to trap gross pollutants and nutrients.

2.2 STUDY AREA

The majority of the study area is located within the catchment of Piles Creek, which is a tributary of Mooney Mooney Creek, and a minor portion of the study area is located within the catchment of Coorumbine Creek. The study area is fully developed and consists of predominantly low-density residential development. Some neighbourhood business developments exist within the study areas. The undeveloped areas within the catchment are mainly National Parks.

The Kariong catchment is located approximately five kilometres west of the Gosford City Central Business District (CBD). The catchment is bounded by the Pacific Highway to the north and Brisbane Water National Park to the east, south and west. The catchment lies between 150 and 200 metres above sea level and is mostly founded on Hawkesbury sandstone.

Woy Woy Road, an arterial road linking the Woy Woy peninsula with the Pacific Highway, traverses the catchment in a north south direction.

3 DATA COLLECTION

A comprehensive search was undertaken to collect the following information:

- contours;
- cadastral data;
- Council's drainage records;
- rainfall data;
- ground survey;
- resident questionnaires; and
- Closed Circuit Television (CCTV) inspection data.

3.1 CONTOURS

Contour details covering all of the study area were provided by Council in digital format. This data was used to define catchment boundaries for each drainage system.

3.2 CADASTRAL DATA

Cadastral data including road and property boundaries, lot numbers and deposit plan numbers were provided in digital format by Council. This data was used to define catchment study limits.

3.3 COUNCIL'S DRAINAGE DATA

Council made available drainage design drawings and work as executed drawings for the study area. This information covered approximately 75% to 80% of the area. Ground level and invert level data were extracted from these drawings for use later in setting up the hydrologic/hydraulic computer models.

Council's Global Information System (GIS) provided digital details on drainage infrastructure location and details on individual pipe diameters and length. This data covered approximately 80% of the study area.

3.4 GROUND SURVEY

Surveyors Johnson Partners were commissioned in February 2001 to provide ground level spot heights in the retarding basins adjacent to Langford Drive and Gilford Street and to provide stormwater pit cover levels and invert levels for where design or work as executed drawings were not available. This data was used to supplement the Council provided drainage data and in constructing the hydrologic/hydraulic computer models. The data was also used to update Council's GIS database. Electronic transfer of data between Gosford Council and AWT Engineering carried out the latter.

3.5 RAINFALL DATA

Design rainfall data for Kariong (Woy Woy Zone) were obtained from Council's Specification for Stormwater Drainage Works (Reference 1). A table outlining the design rainfall intensities is provided in table on the following page.

Duration	Woy Woy Zone (Council)			
	5 year ARI	10 year ARI	20 year ARI	100 year ARI
6 minutes	141	158	181	232
10 minutes	116	131	149	192
20 minutes	86	97	111	143
30 minutes	70	79	91	118
1 hour	48	55	63	82
2 hours	32.2	36.8	42.3	55.5
3 hours	25.3	28.7	33.2	43.7
6 hours	16.6	18.9	22.0	29.0

Table 1Design Rainfall Intensities (mm/h)

Source: Woy Woy Design Rainfall Intensities from Council's Stormwater Drainage Specification

3.6 **RESIDENT QUESTIONNAIRES**

Resident questionnaire forms were delivered to households in those areas that had previously experienced drainage problems. The forms were delivered in early December 2000 and of the 120 forms distributed, 18 (15%) were returned.

The resident questionnaire forms have been supplied to Council under a separate cover (Attachment B).

3.7 CLOSED CIRCUIT TELEVISION (CCTV)

The pipeline inspection company, Pipe Eye Services Pty Ltd, was commissioned in February 2001 to CCTV all pipes greater than or equal to 900 mm diameter. Approximately 3000 metres of pipes were CCTVed and the information captured on videotapes. A report on the condition of the pipes was provided as part of this survey.

The videotapes and conditions reports were provided to Council under a separate cover.

4 HYDROLOGIC AND HYDRAULIC MODELLING

4.1 GENERAL

The hydrologic/hydraulic model adopted for this study was influenced by:

- the quality of the available drainage infrastructure data; and
- the quantity of the available drainage infrastructure data.

During the data collection phase of this study, all of the following drainage infrastructure data was collected:

- pipe sizes;
- pipe lengths;
- pit grate levels;
- pit invert levels;
- location of pipes and pits; and
- topographic details of retarding basins.

The data collected was considered to be good and the latest urban drainage hydrologic/hydraulic model, DRAINS, was adopted. The DRAINS model is capable of utilising all of the data and is considered to be superior to its predecessor ILSAX as it is capable of modelling pipes when under pressure flow.

There are a number of trunk drainage systems in Kariong each with its own outfall. A number of smaller drainage systems also exist with direct discharge into Brisbane Water National Park. To enable better management of the hydrologic/hydraulic modelling the study area was sub-divided into four (4) main catchments (refer to Figure 2), these being:

- Arunta Avenue Catchment (which includes the sub-catchments of Jackson Street and Old Mount Penang Road);
- Belsham Road Catchment;
- Casey Crescent Catchment; and
- Truscott Avenue Catchment.

Details of the existing drainage system in each of the four catchments are shown on Figures 3a to 3d.

4.2 MODEL PARAMETERS

Prior to running the model, model parameters are required. A number of methods are used to determine model parameters. These methods include, in order of preference:

- calibrating the model for at least two historical storm events and then testing the parameters against a third storm event, or
- adopting model parameters from an adjacent catchment that has well documented historical flood data, or
- adopting model parameters from catchments with similar characteristics as the study area.

The study area and its adjacent catchments had very little recorded historical flood data and for this reason model parameters from catchments with similar characteristics to the study area were used. Gosford City Council has prepared numerous urban drainage studies using the ILSAX hydrologic model. The DRAINS model parameters from these studies were assessed and, the parameters adopted for this study are shown in the table below.

Table 2:	DRAINS Model Paramete	rs	
Soil Type	Paved Area Depression Storage (Initial Loss)	Grassed Area Depression Storage (Initial Loss)	Antecedent Moisture Content
2	1 mm	1 mm	3

4.3 SUB-CATCHMENT AREAS

The DRAINS model for the study area is made up of a number of sub-catchment areas (refer to Figures 4a to 4d). Each sub-catchment is joined to an immediately downstream sub-catchment area by a pipe or channel reach. Relevant details of each sub-catchment area required for the model include:

- times of concentration; and
- percentage of impervious and pervious area.

The minimum time of concentration adopted for the study was 6 minutes, as recommended in the 1978 Edition of Australian Rainfall and Runoff. The minimum time was applied to all impervious areas. The times of concentration for pervious areas was estimated using the kinematic wave method described in Council's Specification for Design of Stormwater Drainage Works.

A list of the DRAINS model input data including pipe, pit and retarding basin data and sub-catchment areas are presented in Appendix A.

4.4 HYDRAULICS

The DRAINS model calculates the hydraulic grade lines throughout the stormwater reticulation system and estimates the magnitude of overflows. The hydraulic analysis are dependent on a number of catchment controls, these include:

- outlet water level;
- overland flow paths;
- retarding basins; and
- sag points and associated flood storage capacities.

4.4.1 Outlet Water Level

The study area is at an elevation of between 150 metres and 200 metres above sea level. The majority of the study area drains into Piles Creek with the rest draining into Coorumbine Creek. Both Piles Creek and Coorumbine Creek fall steeply away from the study area and as such have no adverse hydraulic impact on the capacities of the pipe drainage system.

For the hydraulic analyses of the system it has been assumed that the drains have a free outfall.

4.4.2 Overland Flow Paths

When the existing drainage system capacity is exceeded the excess flow is generally transferred to the next downstream inlet pit. The route the excess flow takes is termed as the overland flow path. In most cases the overland flow path is a roadway, however in certain instances it could be:

- drainage easements;
- private property;
- grassed swales;
- open drains; or
- watercourses.

In this study, the overland flow paths are generally roadways and these are accounted for in the DRAINS model by inputting the road cross section and specifying a time of travel for the overland flow. Generally the overland flow travel time was specified as one minute.

4.4.3 Retarding Basins

Retarding basins are drainage structures employed to mitigate peak flows leaving the catchment. The basin temporarily stores the stormwater and its associated peak flow and releases the stormwater at a controlled rate.

4.4.4 Sag Points

Sag points are isolated low points within each catchment. These points can only drain with the assistance of an underground drainage system. Where the underground drainage system is insufficient in capacity, these sag points fill with stormwater and act as mini detention basins. The storage capacities of these sag points are generally small, less than 1000 cubic metres and their impacts on reducing peak flows are negligible, that is, less than two percent. Where the impacts of the sag points are small, the DRAINS model recommends leaving the detention basin out of the model. For the catchments in this study, the storage at sag points is accounted for by providing a storage volume in the sag pit equivalent to the sag point volume. The model then estimates the actual volume of water stored at the sag for each modelled storm event. This data can then later be used to estimate the flood level at each sag point.

4.4.5 Existing System Performance

The DRAINS model for each catchment was run for the 5, 10, 20 and 100 year ARI storm events. Storms durations ranging from 6 minutes to 2 hours were run to determine the worst case storm for each ARI. The worse case model results for each ARI are presented in a separate cover.

The following criteria has been adopted to measure the performance of the existing drainage system:

- Minor overflows flows less than 200 litres per second
- Medium overflows flows between 200 and 600 litres per second
- Major overflows flows greater than 600 litres per second

Overflows have also been converted to depths, and where overflow depths exceed road gutter depths (150 mm), these have been documented on Figures 4a to 4d.

4.4.6 Arunta Avenue Catchment

The DRAINS model results for Arunta Avenue Catchment are provided in the table on below.

Table 3:	DRAINS N	Model Results –	Arunta	Avenue	Catchment
			Riunia	Avenue	Catorinoni

5 year ARI 10 year ARI		20 year ARI	100 year ARI
Minor overflows occur at Gilford St, Hart CI and Turnbull Ave.	Minor overflows occur at Gilford St, Turnbull Ave, Jedda St, Arunta Ave and Taranna Rd.	Minor overflows occur in Langford Dr., Jedda St and Arunta Ave.	Minor overflows occur in Jedda St and Carringa Rd.
Medium overflows occur at Tracie Cl and Jarrah Dr.	Medium overflows occur at Hart CI and Tracie CI.	Medium overflows occur at Gilford St, Hart Cl, Turnbull Ave and Taranna Rd.	Medium overflows occur at Brittany Cr, Jessina St, Gilford St, Turnbull Ave, Langford Dr, Arunta Ave, and Taranna Rd.
-	Major overflow occurs at Jarrah Dr.	Major overflows occur at Tracie Cl and Jarrah Dr.	Major overflows occur at Hart Cl, Tracie Cl and Jarrah Dr.

Rates of flow in Jarrah Drive for the 100 year storm reached a maximum of 1.44 cubic metres per second and maximum depths of 240 mm. This is 90 mm above the top of kerb level. For the 100 year storm event depths of overflow were generally less than 100 mm, the exception being flow across Curringa Road which reached a depth of 220 mm.

4.4.7 Belsham Road Catchment

The DRAINS model results for Belsham Road Catchment are tabled below.

5 year ARI	10 year ARI	20 year ARI	100 year ARI
Minor overflows occur in Vaisey Cl.	Minor overflows occur in Conroy Cres and Belsham Rd.	Minor overflows occur in Conroy Cres.	-
-	Medium overflows occur in Vaisey Cl.	Medium overflows occur at Mitchell Rd South and Vaisey Cl.	Medium overflows occur at Vaisey Cl, Conroy Cres, Carmel Cres and Belsham Rd.
_	Major overflow occurs in Mitchell Dr, between Belsham Rd and the northern end of Mitchell Dr.	Major overflow occurs in Mitchell Dr between, Belsham Rd and the northern end of Mitchell Drive.	Major overflows occur in Mitchell Dr, from Vaisey CI to the northern end of Mitchell Dr.

 Table 4:
 DRAINS Model Results – Belsham Road Catchment

Rates of flow in Mitchell Drive for the 100 year storm reached a maximum of 4.4 cubic metres per second and maximum depths of 300 mm. This is 150 mm above the top of kerb level. This results in a velocity by depth multiple greater than 0.4 m^2/s and is therefore in excess of the upper limit for pedestrian safety.

4.4.8 Casey Crescent Catchment

The DRAINS model results for Casey Crescent Catchment are tabled below.

5 year ARI	10 year ARI	20 year ARI	100 year ARI
Minor overflows occur in Conroy Cres West and Langford Dr West.	Minor overflows occur in Casey Cres.	Minor overflows occur in Langford Dr East.	Minor overflows occur in Thurling Ave.
-	Medium overflows occur in Conroy Cres West, Carmel Cres and Langford Dr West.	Medium overflows occur Conroy Cres, Carmel Cres and Casey Cres.	Medium overflows occur in Langford Dr East.
-	-	Major overflow occurs in Langford Dr.	Major overflows occur in Conroy Cres, Carmel Cres and Langford Dr West.

 Table 5:
 DRAINS Model Results - Casey Crescent Catchment

The greatest rate of overflow in this catchment occurs in a drainage reserve downstream of Dean Place. For the 100 year storm, the overland flow reached a maximum of 1.4 cubic metres per second and a maximum depth of 160 mm. This results in a velocity by depth multiple of approximately 0.4 m^2 /s, which is the upper limit for pedestrian safety.

For the 100 year storm event, the depth of overland flow in the street gutters is generally less than 200 mm.

4.4.9 Truscott Avenue Catchment

The DRAINS model results for Truscott Avenue Catchment are tabled on the following page.

Table 6: DRAIN	Fable 6: DRAINS Model Results – Truscott Avenue Catchment				
5 year ARI	10 year ARI	20 year ARI	100 year ARI		
Minor overflows occur in Oaks St, Benkari Ave and Truscott Ave South.	Minor overflows occur in Maher Cl, Howe Pl, Langford Dr and Risdon Cres.	Minor overflows occur in Cutcheon St, Rees St and Barclay Cl.	Minor overflows occur in Cutcheon St, Whitehead Cl and Barclay Cl,		
-	Medium overflows occur in Oaks St, Benkari Ave and Truscott Ave south	Medium overflows occur in Maher Cl, Hempstalk Cres, Howe Pl, Oaks St, Benkari Ave and Truscott Ave.	Medium overflows occur in Hempstalk Cres, Howe PI and Rees St.		
_	-	Major overflow occurs in Langford Dr.	Major overflows occur between Old Woy Woy Rd and Kari Cl and in Maher Cl, Oaks St, Langford Dr and Benkari Avenue.		

The greatest rate of overflow in this catchment occurs in Langford Drive near Oaks Street. For the 100 year storm, the overland flow reached a maximum of 2.15 cubic metres per second and a maximum depth of 165 mm. This results in a velocity by depth multiple of approximately 0.4 m2/s, which is the upper limit for pedestrian safety.

For the 100 year storm event, the depth of overland flow in the street gutters is generally less than 200 mm.

5 RESIDENT QUESTIONNAIRES

Resident questionnaire forms were distributed to 120 households in the catchment. The households were selected on the basis of previously reported drainage problems and a study of the contours for each catchment also identified potential drainage problem areas.

The forms were delivered in early December 2000 and of the 120 forms distributed, 18 (15%) were returned.

The resident questionnaire forms have been supplied to Council under a separate cover (Attachment B).

The questionnaires identified 4 main areas of drainage problems (Figure 7). These being at:

- Jarrah Drive Old Mt. Penang area, Area A
- Tudawali Crescent Arunta Avenue area, Area B
- Foster Close and Woodley Close area, Area C
- Maher Close and Percy Joseph Avenue area, Area D

Area A - Jarrah Drive

Three resident questionnaires were received from this area with all three reporting past flooding experience. This supports the hydraulic modelling which identified that the pipe drainage system in the Jarrah Drive area surcharges (overflows) for the 5 year ARI storm event.

Area B - Tudawali Crescent - Arunta Avenue area

Four resident questionnaires were received from this area with all reporting past flooding experience. However, all four questionnaires also indicated that since the construction of additional drainage systems in the area, they had not experienced further flooding. This supports the hydraulic modelling which shows that the drainage system in the Arunta Avenue area can cope adequately for all storms up to the 100 year ARI event.

Area C - Foster Close and Woodley Close area

Two resident questionnaires were received from this area. One questionnaire identified minor backyard flooding due to a lack of inter-allotment drainage whilst the other questionnaire mentioned that the drainage problem had been addressed by Council. The hydraulic modelling was established to mainly investigate the existing trunk drainage system and therefore would not detect drainage problems at the inter-allotment level.

Area D - Maher Close and Percy Joseph Avenue area

Four resident questionnaires were received from this area. Three were received from Maher Close and one from Percy Joseph Avenue. The questionnaire received from Percy Joseph Avenue reported no incidents of flooding. The main drainage problem for Maher Close residents was runoff from the National Park. The hydraulic modelling shows that overland flows of up to almost one cubic metre per second for the 100 year storm event could be expected in Maher Close.

6 CLOSED CIRCUIT TELEVISION (CCTV)

The pipeline inspection company Pipe Eye Services Pty Ltd, was commissioned in February 2001 to CCTV all pipes greater than or equal to 900 mm diameter. Approximately 3000 metres of pipes were CCTVed and the information captured on videotapes. The locations of the pipes surveyed are shown on Figures 6a and 6b.

The videotapes and conditions reports by Pipe Eye Services Pty Ltd were provided to Council under a separate cover.

The full analyses of the faults in the pipelines are attached as Appendix C.

A list, of the common faults, is as follows:

- Direct connection of small pipes to the trunk drains. These usually consisted of 100 mm diameter sub-soil drains and roof drainage lines. The break into the larger pipes leaves the reinforcement exposed, leading to rusting of the reinforcement and weakening of the pipe. The holes created in the trunk drain for the direct connection were usually oversized and this allows groundwater and sediments to flow into the trunk drain. Consequences of this are loss of backfill material and conveyance of sediments into the receiving watercourse. Additionally, the 100 mm diameter pipes were often installed such that 200 mm to 500 mm of the smaller pipe intruded into the trunk drain and adversely affected the hydraulic performance of the trunk drain.
- Leaking pipe joints between Pit A8 and Pit A22. Flush joint pipes were installed in this section of drainage line and these allow groundwater and sediments to drain into the pipe. The loss of backfill has resulted in adjacent pipes being displaced relative to each other.
- All pipes are manufactured with a lifting hole which are sealed with a concrete block before placement of backfill. On average between 30 and 40 percent of all lifting holes were not watertight and allowed both groundwater and sediments to flow into the trunk drain.

The structural condition of the pipes surveyed were generally in good condition except for a few cases of circumferential cracks and one case where there was significant pipe damage in the 450 mm pipe located under Woy Woy Rd. This is shown as pipe G11 to G12 on Figure 6a.

DRAINAGE MANAGEMENT STUDY 7

This section of the study reviews the behaviour and performance of the existing drainage system for the 5 year, 10 year, 20 year and 100 year storm events. The existing system performance is compared with the drainage standard set out in Council's specification for drainage design for a residential area and drainage management works are proposed.

The existing drainage systems are shown on:

- Figure 3a Arunta Avenue Catchment;
- Figure 3b Belsham Rd Catchment; •
- Figure 3c Casey Crescent Catchment; and •
- Figure 3d Truscott Avenue.

Council's drainage standards for a residential area are set out in the following table:

Table 7: Council's Drain	hage Standards	
Drainage Situation	Design Flood Average Recurrence Interval	Excess Flow Passage
1. Residential streets and catch drains with overflow or bypass along the street.	10 Year	The 100 year flood to be confined to carriageway, pathway or reserve.
2. Residential streets and catch drains at low points with overflow along public reserves and pathways.	10 Year	The 100 year flood to be confined to carriageway, pathway or reserve.
3. Residential streets and catch drains at low points with drainage lines traversing building allotments or other locations where surface flow may cause property damage.	Generally 20 year, but 100 year if there is no escape route	The 100 year flood edge of stream is to be shown on the plans so that appropriate easement width and treatment of escape route can be determined.
4. Major system traversing developed areas (residential, commercial or industrial). Major systems are defined as those having catchment areas in excess of 15 ha. Or having 50 year ARI runoffs in excess of 3 m ³ /s whichever is the lesser.	Generally 50 year, but 100 year if there is no escape route	The 100 year flood edge of stream is to be shown on the plans so that appropriate easement width and treatment of escape route can be determined.

~

7.1 **ARUNTA AVENUE CATCHMENT**

In section 4.4.6 it was noted that minor sections of the existing drainage system, in this catchment, fail to meet the design requirements in "Drainage Situation 2" as set out in Council's Specification for Drainage Design. However, a more detailed study of the impacts of the under-capacity sections of pipelines shows that the overland flows for up

to the 100 year storm event do not pose a pedestrian safety hazard. The velocity times depth multiple is less than $0.4 \text{ m}^2/\text{s}$.

7.1.1 Old Mount Penang Road Sub-Catchment

In Jarrah Drive, the floodwater during a 100 year storm event has been estimated to overtop the kerb by 90 mm. The overland flowpath downstream of the Jarrah Drive low point is via private property.

Recommended drainage works, for this catchment, are:

- provide an additional 675 mm diameter pipe between Jarrah Drive and Pacific Highway;
- provide additional collection in Jarrah Drive (up to 4 extended kerb inlet pits); and
- create a drainage easement/overland flowpath through Lot 59 in DP 250926 and Lot 2 in DP 581761.
- The estimated cost of works is \$50,000.

OR

- provide a retarding basin in the existing park; and
- create a drainage easement/overland flowpath through Lot 59 in DP 250926 and Lot 2 in DP 581761.
- The estimated cost of works is \$50,000.

7.2 BELSHAM ROAD CATCHMENT

In this catchment, parts of the existing drainage system fail to meet:

- the design requirements in "Drainage Situation 2" as set out in Council's Specification for Drainage Design; and
- the need for the overland flows "velocity times depth multiple" to not exceed 0.4 m²/s, which is upper the limit for pedestrian safety.

The recommended drainage works, for this catchment, are:

 duplicate existing pipeline in Mitchell Drive between Belsham Rd and northern end of Mitchell Drive. Estimated cost of works is \$430,000.

7.3 CASEY CRESCENT CATCHMENT

In section 4.4.8 it was noted that minor sections of the existing drainage system for this catchment fail to meet the design requirements in "Drainage Situation 2" as set out in Council's Specification for Drainage Design. However, a more detailed study of the impacts of the under-capacity sections of pipelines shows that the overland flows for up to the 100 year storm event do not present a pedestrian safety hazard - velocity times depth multiple is less than 0.4 m²/s.

Council has previously received reports of flooding in the Woodley Close – Foster Close area. Flooding was caused mainly by flows coming off the basketball courts in the Kariong School grounds. To address this problem, it is recommended that Council provides additional drainage in Foster Close to intercept runoff from basketball courts before it flows across the road and into the Public Reserve on the low side of Foster Close. The estimated cost of works is \$25,000.

Council has received reports of groundwater problems in the Carmel Crescent, however, this issue was outside the scope of this study and has not been addressed.

7.4 TRUSCOTT AVENUE CATCHMENT

In section 4.4.9 it was noted that minor sections of the existing drainage system for this catchment fail to meet the design requirements in "Drainage Situation 2" as set out in Council's Specification for Drainage Design. The drainage model results are supported by comments received from the public, following the advertising of the Draft Exhibition report in December 2001 – January 2002. The public comments stated that considerable volumes of surface stormwater runoff originated from the grounds of the Kariong Public School and caused nuisance flooding in Truscott Avenue. It is therefore recommended that additional pipework and stormwater collection pits be provided in Truscott Avenue. The estimated cost of the works is \$160,000.

The resident interviews showed that there are excessive overland flows from Brisbane Water National Park that drain into properties fronting Maher Close. There are existing cut-off drains that divert runoff into Maher Close. In large storm events the cut-off drain capacity is exceeded and the overflow drains into the rear yards of properties fronting Maher Close. To mitigate this problem it is recommended that Council enlarge the cutoff drain and/or provide a levee to at least 20 year capacity. The estimated cost of works is \$8,000.

8 WATER QUALITY

8.1 GENERAL

The quality of stormwater that flows off a developed catchment is very much governed by its land usage, ie its zoning. The Kariong drainage catchment has a total area of 210 hectares and is primarily zoned Residential 2 (a). Recent studies on the main pollutant and typical loads conveyed by stormwater for an urbanised area are provided in the table below.

Table 8:	Typical Pollutant Loads in Urban Stormwater

Pollutant	Dry Weather Concentration	Wet Weather Event Mean Concentration
Gross Pollutants & Gravel	*	*
Suspended Solids (mg/L)	1 – 350	20 – 1000
Nutrients:		
Total Phosphorous (mg/L)	0.001 – 2.200	0.12 – 1.60
Total Nitrogen (mg/L)	0.1 – 11.6	0.6 - 8.6

(Source: Suspended Solids and Nutrients from EPA's Managing Urban Stormwater – Strategic Framework 'Draft', September 1996)

Variable and very much dependant on individual catchments. Could potentially reduce over the coming years due to the EPA's current education program.

The CCTV work that was carried out for this study highlighted copious amounts of sediment and building rubble in the drain in Woy Woy Rd (Reference Line A on Figure 6b). There has been recent sub-division work and new homes constructed in the area upstream of this drain and this is the most likely source of the sediments and building rubble.

The video tapes from the CCTV work carried out in the rest of the study area shows that the pipes are relatively free of sediments. Vegetation matter, in the form of large twigs and roots, were common in the section of drain located beneath the retarding basins in the Truscott Avenue catchment. In one pit the vegetation debris caused a loss of about 20% of the pipe inlet area.

A visual inspection of the wetland downstream of Kariong Oval and at the northern end of Mitchell Drive shows that gross pollutants in the form of soft drink containers, food packaging, paper, etc. was finding its way into the wetland.

The four (4) wetlands located immediately west of and adjacent to the study area (Casey Crescent Catchment) were found to be in good condition following a visual inspection in April 2001. At the end of the stormwater pipe conveying flow to the wetland, a headwall and trash rack was installed. At the time of inspection the trashracks and the wetlands were generally clean of debris and the water in the wetland was free of floating algae.

8.2 WATER QUALITY RECOMMENDATIONS

The following actions/works have been recommended to improve water quality:

- provide vegetation/debris trap at inlet to the retarding basin pipe drainage system upstream of Langford Drive and between Hempstalk Crescent and Oaks Street;
- provide a gross pollutant trap immediately upstream of the wetland in the Recreation Reserve and at the northern end of Mitchell Drive; and
- enforce Council's erosion and sediment controls on land sub-dividers and home constructers.

9 WATER SENSITIVE URBAN DESIGN

Traditionally, urban stormwater management has concentrated on stormwater drainage and flood protection to accommodate the expected increase in stormwater discharge due to the catchment urbanisation. (Wong and Eadie, 2000) Water Sensitive Urban Design (WSUD) is a relatively new concept which aims at managing urban stormwater within an ecological and sustainable framework where wastewater and stormwater are recycled and potable supplies are conserved. The principles of WSUD are based on total catchment water management and implementation of best practices currently used in the water industry. Key elements of WSUD can be integrated into the planning, design, construction, management and landscaping of individual homes, factories, precincts and industrial estates, eg reuse of stormwater in groundwater recharge, toilet flushing, for irrigation and in hot water supply systems. (Stormwater Industry Association, 2000 and Coombes et al, 2000).

The cost of upsizing existing and rebuilding aging stormwater infrastructure can be costly for large catchments, so by making WSUD features part and parcel of development applications, it may be possible for Council to minimise the stormwater impact of new developments. In making it mandatory for new developments to retain and recycle most stormwater at the source the amount of stormwater that enters already deficient network will be reduced. This therefore reduces the amount Council needs to spend upgrading the stormwater infrastructure. Besides large cost savings WSUD also provides significant environmental benefits.

For WSUD to be successful it will be necessary for Regulators and Authorities to amend policies on:

- · the quality of stormwater that can be discharged from a development site; and
- the quantity of stormwater runoff that is permitted to be discharged from a development site.

Reduced stormwater discharge from a development site, could be achieved by reuse and reduced runoff via clever landscaping, water tanks, roof gardens, bio-retention, rainsaver gutters, groundwater recharge, etc..

The rate of implementation of WSUD is controlled by Regulators and Authorities and by financial incentives. Roof gutters are on average replaced every 15 to 20 years on domestic dwellings. Financial incentives to replace existing gutters with more expensive rainsaver gutters and water tanks will be required to encourage uptake of the concept by developers and home owners.

Research has shown that WSUD can reduce the quantity of runoff from a residential sub-division by about 50% and potable water consumption by a similar percentage. The reduction in potable water demand can delay the need to upgrade water mains by up to 18 years. (Coombes et al, 2000-reference 3) This should provide an incentive to both water supply authorities and consumers.

Council's Development Control Plan for Kariong might be amended to include a guide for the re-development of the area and recommend:

Water conservation to:

Minimise the use of reticulated water on site through conservation practices and reuse of rainwater.

All new developments are to include water saving devices such as dual flush toilets, tap aerators, spring return taps and low water use dishwashers and washing machines.

Site Drainage and Stormwater Control:

Development should be designed to ensure maximum rain water infiltration on site by minimising paved areas and providing stormwater drainage systems that promote natural infiltration.

All new developments to include rainwater tanks and/or rainsaver gutters. Stormwater stored in such devices is not to be used for consumption but to be used for irrigation, toilet flushing, car washing etc..

Council might consider providing a financial incentive to residents who implement WSUD from the savings it would make by not having to upgrade its existing infrastructure.

10 COSTING OF WORKS

Each component of the drainage works recommended to upgrade the drainage system standard to Council's latest standard, improve water quality and repair structurally defective sections of the drainage system, were costed, and this is represented in Appendix D. A summary of the costs for each of the four sub-catchments is tabled below.

Catchment	Proposed Work	Cost
Arunta Avenue	Upgrade drainage line between Jarrah Drive and Pacific Highway and provide additional pits in Jarrah Drive, or provide a retarding basin in Jarrah Park. This excludes the cost of acquiring a drainage easement between Jarrah Drive and Pacific Highway.	\$50,000
	Fix leaking pipe joints between Langford Drive and Taranna Rd (340 metres at \$350/metre).	\$140,000
Belsham Road	Duplicate pipe drainage system in Mitchell Drive between Belsham Rd and northern end of Mitchell Drive.	\$430,000
	Provide and maintain a GPT in the Recreational Reserve adjacent to Mitchell Drive.	\$50,000
Casey Crescent	Provide drainage in Foster Close.	\$25,000
Truscott Avenue	Upgrade existing cutoff drain and levee at the rear of properties fronting Maher Close.	\$8,000
	Provide a trash rack at the entrance to the pipe system under the retarding basins.	\$70,000
	Replace existing 375mm and 450mm pipes across Woy Woy Rd with a single 900mm culvert. Reconstruct pit over existing 900mm pipe to accommodate new pipe connection and to improve inlet hydraulics.	\$25,000
	Provide additional drainage in Truscott Avenue	\$160,000
General Repairs in all four catchments	Seal leaky pipe joints and bung holes (pipe lifting holes).	\$100,000
	Trim all agricultural pipe connections into trunk mains, paint exposed reinforcement with coal tar epoxy and mortar spalled concrete with epoxy cement.	\$50,000
	Repair cracked pipes with epoxy cement.	\$50,000
Wetland Maintenance	Maintain existing wetlands.	\$20,000
(Casey Street and		per
Truscott Avenue catchments)		annum

Table 9:Cost of Works

11 DRAINAGE MANAGEMENT PLAN

The drainage management plan (Figure 8) presented in this report has been selected on the basis of:

- meeting Council's latest specification for the design of stormwater drainage works;
- providing protection to the environment by recommending the installation of gross pollutant traps and trash racks and the enforcement of Council's Erosion and Sediment control policy;
- providing protection of public and private assets by recommending and prioritising maintenance works on the existing drainage infrastructure; and
- promoting the conservation of natural resources by recommending the adoption of the principles of Water Sensitive Urban Design.

The upgrade works recommended in the management plan have been ranked ie. given a priority based on returned questionnaires and historical knowledge of areas most likely to be flooded in a storm event. The following table outlines the proposed works and their priority.

ltem	Proposed Works	Priority
A	Construct a retarding basin in Jarrah Park and acquire a drainage easement over the existing 525 mm pipe between Jarrah Drive and Pacific Highway. Cost \$50,000.	HIGH
В	Fix leaking pipe joints between Langford Drive and Taranna Road. Cost \$140,000.	MEDIUM - HIGH
С	Duplicate pipe system in Mitchell Drive, between Belsham Road and the north end of Mitchell Drive. Cost \$430,000.	LOW
D	Provide and maintain a Gross Pollutant Trap in the Recreational Reserve adjacent to Mitchell Drive. Cost \$50.000.	LOW - MEDIUM
E	Provide additional drainage in Foster Close. Cost \$25,000.	HIGH
F	Upgrade existing cut off drain and levee at rear of properties fronting Maher Close. Cost \$8,000.	HIGH
G	Provide and maintain a trash rack at the entrance to the retarding basin between Hempstalk Crescent and Oaks Street. Cost \$70,000.	MEDIUM
Н	Replace existing 375 mm and 450 mm pipes across Woy Woy Road with a 900 mm pipe. Reconstruct pit on the western side of Woy Woy Road. Cost \$25,000.	HIGH
J	Provide additional drainage in Truscott Avenue.	HIGH
	Cost \$160,000.	
<u>General V</u>	<u>Vorks</u>	
Seal I	eaky pipe joints and bung holes. Cost \$100,000.	MED
 Trim a pipes. tar ep \$50,0 	all small diameter uPVC pipes intruding into the trunk drainage Remove rust from exposed reinforcement and paint with coal boxy. Repair spalled concrete around reinforcement. Cost 00.	MED
Repai	r cracked pipes with epoxy cement. Cost \$50,000.	HIGH
Maintena	nce Works	
Maintain Cost \$20	existing wetlands in Casey Cres and Truscott Ave Catchments. , 000 per annum.	HIGH

Table 10:Proposed Drainage Works

12 **REFERENCES**

- P Coombs, G Kuczera, J Argue and J Kalma,
 Costing of Water Cycle Infrastructure Savings Arising from Water Sensitive Urban Design Source Control Measures
 WSUD Conference, Melbourne, August 2000
- Department of Housing Kariong, Upper Catchment Drainage May 1990
- Gosford City Council
 Specification for the Drafting and Design of Stormwater Drainage Works and Roadworks
 Revised Edition September 1993
- The Institute of Engineers, Australia
 Australian Rainfall and Runoff A Guide to Flood Estimation Revised Edition 1987

13 GLOSSARY OF TERMS

Afflux

Change in water surface profile due to head losses due to changes in channel crosssection, alignment or obstruction.

Annual Exceedance Probability (AEP)

Refers to the probability or risk of a flood of a given size occurring or being exceeded in any given year. A 90% AEP flood has a high probability of occurring or being exceeded: it would occur quite often and would be relatively small. A 1% AEP flood has a low probability of occurrence or being exceeded; it would be fairly rare but relatively large.

Australian Height Datum (AHD)

A common national plane of sea level corresponding approximately to mean sea level.

Average Recurrence Interval (ARI)

The expected or average value of the time period between exceedances of a given event magnitude.

Catchment

The area draining to a site. It always relates to a particular location and may include catchments of tributary streams as well as the main stream.

Designated Flood

See flood standard.

Detention Basin

A temporary storage that fills during a storm event and effectively throttles flow out in order to reduce the peak discharge.

Discharge

The rate of flow of water measured in terms of volume over time. It is to be distinguished from velocity of flow, which is a measure of how fast the water is moving rather than how much is moving.

Flood Hazard

Potential for damage to property or persons due to flooding.

Flood Standard

The flood selected for planning purposes. The selection should be based on an understanding of flood behaviour and the associated flood risk. It should also take into account social, economic and ecological considerations.

Hydraulic Grade Line (HGL)

This line indicates the water levels in a drainage system for a given flow. It represents the piezometric head and is a direct measure of the static pressure in the flow.

Hydraulics

The term given to the study of water flow in a watercourse or piped drainage system, in particular, the evaluation of flow parameters such as stage (or water level) and velocity.

Hydrograph

A graph that shows how the discharge varies with time at any particular location.

Hydrology

The term given to the study of the rainfall and runoff process as it relates to the derivation of hydrographs for given floods.

IFD Data

Intensity – Frequency – Duration data provides average rainfall intensities for a range of average recurrence intervals and design storm durations based on historical data.

Management Plan

A document including as appropriate, both written and diagrammatic information describing how a particular area of land is to be managed to achieve defined objectives. It may also include description and discussion of various issues, problems, special features and values of the area, the specific management measures that are to apply, and the means and timing by which the plan will be implemented.

Mathematical/Computer Models

The mathematical representation of the physical processes involved in runoff and streamflow. These models are often run on computers due to the complexity of the mathematical relationships. In this report, the models referred to are mainly involved with rainfall, runoff and streamflow.

Peak Discharge

The maximum discharge occurring during a flood event.

Probability

A statistical measure of the expected frequency or occurrence of flooding. For a fuller explanation, see Annual Exceedance Probability.

Rational Method

A statistical method for use in estimating design flows. It is used to estimate a peak flow of a selected ARI from an average rainfall intensity of the same ARI.

Runoff

The amount of rainfall that actually enters the drainage system or watercourse; also known as rainfall excess.

Stormwater Flooding

Inundation resulting from the incapacity of an urban stormwater drainage system to handle runoff.

Tailwater Level

The level in some downstream receiving water or control structure which influences water levels in the upstream system.

Water Surface Profile

A longitudinal plan showing the flood stage at any given location along a watercourse or drainage system.











COMMEN	IS - LINE	G					
Se	ction	Pipe	Total	Chainage	Deposition of Defost	Ranking	Decomposided Works
From	То	(mm)	(m)	(m)	nescription o person	Defect	
G05	G06	900	24	24.5	- tree roots in Pit G06	н	remove tree roots from Pit G06
G06	G07	900	14	14.5	- twigs in Pit G07	н	remove vegetation matter from Pit G07
G07	G08	906	22	0.1	- circumferential crack in pipe	м	clean crack and repair with epoxy cement

F10 FIO

F11

600 750

26

– no major problems, so OK - roots at upstream opening (F11)

7

7.0

F13

F12

900

35

29.0 11.6

150mm service pipe (watermain ?) through top of pipe

r т

trim intruding pipe, clean reo, and repair with epoxy cement check if service pipe is live, if not remove service pipe and repair stormwater pipe

±

remove vegetation and install a trash rack at pipe entry

intruding ag pipe, reo exposed significant seepage via pipe joint F08

F09

1050

29

11.5 26.7

0.0 - 20.0

debris along pipe invert - sand bags, gravel, etc.

obstruction (tree root/branch) in pipe

т т т

remove debris

emove debris

lean pipe joint and seal with epoxy mortar

70.1 30.9 67.7 18.2

debris at pit

F07

F08

600

70

pipe broken near invert

debris in pipe

seepage at pipe joint, also at Chainages 36.5, 50.0 and 52.9 significant seepage via pipe joint

ΞΞ

clean area and repair with epoxy cement clean pipe joint and seal with epoxy mortar clean pipe joint and seal with epoxy mortar

т

emove debris

z

move debris

F02 F03

F01 F07

1050 1050 1350

29 53

1.5 - 6.3 0.0 1.0

3 small pipe connections, rust staining pipe
 debris at mouth of upsteam opening (Pit F02)

т – ×

nonitor the situation

remove debris - good location for dry GPT at outlet

34.0

spalled concrete at pipe obvert poor small pipe connection - reo. Exposed

F04

F03

600

49

4.5 5.0

F06 F06

600

33 & 35.6

- substantial seepage via pipe lifting holes

poor pipe to pit connection, pipe reo. rusting and

exposed.

ĸ

remove silt from pipe invert clean pipe lifting holes and seal with epoxy cement

clean exposed reo. and repair pipe with epoxy morta

т

53.5

0.0 - 1.0

- silt along pipe invert

From Section

Pipe Diameter (mm)

Length (m)

Chainage (m)

Description of Defect

Ranking of Defect

Recommended Works

1200

F05

F04 F05 F12 ī

1050

34 0 4 47

- no major problems, so OK

circumferential crack, reo. rusted & significant seepage

seepage at pipe joint, also at Chainages 31.0, 33.6, 36.5, 38.6, 41.1

5 5 I

clean around pipe connection and repair with epoxy cement

lean area and repair with epoxy cement

clean exposed reo. and repair pipe with epoxy mortar

lean pipe joint and seal with epoxy mortar

RISDO JAMES 5 RES E۷ E3 ENVER ¶L_E HAYTER F1 F2 8 CUTCHEON J 5 \$ 74 9LE JAN F12 2'n F8 F9 F10 F1 ER. FTZ

ro F	FO?	1	E01			FOR			FO.3	From	Sec
10	F04	1	E05		Į	F07		100	FOR	5	tion
-000	1050		1050			900			900	(mm)	Pipe
ō	48	;	48		1	38		8	3	(n)	Total
48.3	32.0	50.0	35.5	18.9	17.2	16.4	16.2	32.7	28.5	(m)	Chainage
 debris obstructs upstream inlet to culvert 	- poor small pipe connection near side - reo. Exposed	 log obstructs upstream inlet to culvert 	– poor small pipe connection near obvert – reo. Exposed	– poor small pipe connection near obvert – reo. Exposed	- poor small pipe connection at obvert - reo. Exposed	– open pipe joint – medium	 poor small pipe connection at obvert - reo. Exposed 	- damaged pipe lifting hole	- poor small pipe connection at obvert - reo. Exposed		Tananaistian at Takina
т	т	т	т	т	×	×	x	-	z	Defect	Ranking
remove obstruction and install a trash rack	clean around pipe connection and repair with epoxy cement	remove obstruction and install a trash rack	clean around pipe connection and repair with epoxy cement	clean around pipe connection and repair with epoxy cement	clean around pipe connection and repair with epoxy cement	clean pipe joint and seal with epoxy mortar	clean around pipe connection and repair with epoxy cement	clean pipe lifting holes and seal with epoxy cement	clean around pipe connection and repair with epoxy cement		Decommended Works

COMMENTS - LINE F

COMMENTS - LINE E



	pipe to be unblocked	т	- pipe not CCTV surveyed permanently full of water				A22	A33	
	clean pipe unblock downstream pipe	тт	 debris (including silt) in pipe water level is 40% past CH13.1 	1.4 13.1	13	1050	A33	A34	
	repair broken conduit with epoxy cement	м	- broken conduit at CH23.7 and CH25.4	23.7 & 25.4	31	1200	7A	A7A	
			– no major problems, so OK		59	1200	A7A	A6	
Image Image <t< td=""><td>clean pipe joints and mortar with epoxy cement</td><td>x</td><td>- most joints leak between CH2.5 and CH84.4</td><td>2.5 - 84.4</td><td>84</td><td>825</td><td>A5</td><td>A6</td></t<>	clean pipe joints and mortar with epoxy cement	x	- most joints leak between CH2.5 and CH84.4	2.5 - 84.4	84	825	A5	A6	
Image:	ann manang pipes a sear aroann marannig pipes	-	- including pipes or criticity, criticity on or responses of OK		64 d	1200	A5 74	\$	
Image:	trim intruding pipes & seal around intruding pipes		- intruding pipes at CH34.2, CH45.1, CH66.1 and CH 72.5		: 7	1050	A3	5 A	
Image:			– no major problems, so OK		40	1200	A1	A2	
Image:	check pipe and remove/ re-route	т	- small dia. pvc pipe running through Pit A11	30.1					
Image:	remove roots and epoxy mortar point of root entry	×	- fine roots at joints	16.3 & 22.9	30	1050	A11	A12	
Image:	clean pipe joints and mortar with epoxy cement	<	– no major problems, so UK – most joints leak between CH5.7 and CH30.1	5.7 - 30.1	`	ODR	A12	AIS	
	repair displaced pipe joint	×	- pipe joint aisplaced - meaium	282	۲	200	010		
Image:	repair displaced pipe joint	: т	- pipe joint displaced - large	23.72					
Image:	trim intruding pipes & seal around intruding pipes	x	 intruding pipes at CH17.6 and CH19.7 	17.6 - 19.7					
Image:	clean and repair with epoxy cement	x	- leaking joints between CH14.0 and CH30.1	14 - 30.1	30	006	A14	A13	
Image: Protect interval	repair displaced pipe joint	т	- pipe joint displaced - large	6.9					
Image:	repair displaced pipe joint	т	– pipe joint displaced – medium	1.7					
Image: Interpret inter	trim intruding pipes & seal around intruding pipes	т	- intruding pipes at CH56.7 and CH 56.8	56.7					
Image: Interpret inter	clean around connection and mortar with epoxy cement	т	- pipe connection	14.8	94	1350	A07	A08	
Image: Second	clean and repair with epoxy cement	x	 break in conduit (exposed reinforcement) 	0					
VertureVertureVertureCurrently in primeNumber in the prime <td>clear roots and repair pit with epoxy cement</td> <td>z i</td> <td>- roots in Pit A08</td> <td>95</td> <td></td> <td></td> <td></td> <td></td>	clear roots and repair pit with epoxy cement	z i	- roots in Pit A08	95					
SummerVertureVertureCharacteristic statusSummarize statusSu	trim intruding nines & seal ground intruding nines	c :	- intruding pipes	2 0 7					
Image: problemImage: problemImage	clear roots and repair pipe joint with epoxy cement	. 1	- roots at joint	8.3	95	1200	A08	A09	
Symmetry Vertex Transmission Transmission <thtransmission< th=""> <thtransmission< th=""></thtransmission<></thtransmission<>	trim intruding pipe & seal around intruding pipe	т	 intruding concrete pipe 	5.8					
System Description of label; Resummed Work $\frac{1}{100}$ $\frac{1}{100}$ $\frac{1}{100}$ $\frac{1}{100}$ $\frac{1}{1000}$ $\frac{1}{10000000000000000000000000000000000$	clear roots and repair pipe joint with epoxy cement	т	- roots at joint	1.3					
Sector Form Form Form Form Reconcerned work Form Reconcerned work $1-10^{-10}$ 6^{-10} 5^{-10} $1-10^{-10}$ Form	check cross connection & trim intruding pipe	т	- cross connection obstructing pipe opening in Pit A11	32.7					
Seture Temperature Temperature <thtemperature< th=""> <thtemperature< th=""> <th< td=""><td>clean and repair with epoxy cement</td><td>т</td><td> open joint and noticable seepage </td><td>3.3</td><td>1</td><td></td><td></td><td></td></th<></thtemperature<></thtemperature<>	clean and repair with epoxy cement	т	 open joint and noticable seepage 	3.3	1				
Series Image: Series Image: Series Image: Series Image: Series Se	clear roots and repair with epoxy cement	x	- fine roots coming through pipe joint	3.3	32	1050	A11	A10	
Instant Vertication of back Characterization of back Vector Characterization of back Vector Resonanced wave N_{12}	clear roots and repair with epoxy cement	I	- mass of roots at mouth of conduit (Pit A10)	0					
Beam Vert Description of huber, Vert Description of huber, Vert Resonance with what N_{10} R_{10} R_{10		ī	– no major problems, so OK		9	1050	A10	A09	
Senter Image: Senter in the sentencial crock at the of pie and approximate according to the pie and	trim intruding pipe & seal around intruding pipe	т	- CCTV survey abandoned because of intruding pipe	32.7					
Sector Fran For Fo	trim intruding pipes & seal around intruding pipes	т	- intruding small dia. ag & plastic pipes	30.7	32.7	006	A13	A14	
Sector Sector Description of Defect Recommended Works rmm r_m	clear roots and repair with epoxy cement	I	 fine roots opening pipe joint 	27.2					
Section Image (a) Image (a) <th< td=""><td>clean and repair with epoxy cement</td><td>- I</td><td>- no major provienna, so on - substantial seepage via most pipe joints</td><td>6.4 - 32.7</td><td>u</td><td>900</td><td>1</td><td>3</td></th<>	clean and repair with epoxy cement	- I	- no major provienna, so on - substantial seepage via most pipe joints	6.4 - 32.7	u	900	1	3	
Section intervential intervential Construction of large in the problem Intervential Construction of large in the problem Intervential Construction Conston Conston Construct	ciean and repair with epoxy cement	ц	- pipe joint aamage at invert	10.1		200			
Senter Image: Senter Image: Senter Senter Recommendation Image: Senter Recommendation 1707 100 100 100 100 100 100 100 100 100 100 100 10000 $1000000000000000000000000000000000000$	trim intruding pipe & seal around intruding pipe	: 3	- intruging plastic pipe	40 4 - 44 1					
Important in the interval of the interval	clean and repair with epoxy cement	т	 break in conduit (exposed aggregate) 	26.5					
Symphoton Tem To Form To Encontracted work Form To Encontracted work Encontracted wo	clear debris and repair with epoxy cement	т	- debris at badly damaged joint (concrete)	25.8					
Sector Term In Feature interval Description of Defect In Recommendate Worka $\frac{1}{12}$	clean and repair with epoxy cement	т	 break in conduit (exposed reinforcement) 	24.9	71	900	A15	A18	
Section Interview Interview Interview Description of Duffet Free momenda Work $\frac{1}{100}$ 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.3 6.1	clean and repair with epoxy cement	т	– substantial seepage via most pipe joints	12.5 - 41.0					
System Image: System Image: System Recommended Works Recommended Works $rem no 120 5.7 examinemic cock at top of pipe of near origing any any any system N Recommended Works N \Lambda R \Lambda R 1200 56.2 27.9 Image: System N Image: System N N \Lambda R \Lambda R 1200 61 51.4 sign of near on-pipe wall (seepage ?) Image: System N Image: System N \Lambda R \Lambda R R R R R R R R R R R R R R R R R \Lambda R $	trim intruding pipe & seal around intruding pipe	×	 Ø100mm connection intrudes 100mm 	7.7					
Image: Section Image: Section Image: Section S	clean and repair with epoxy cement	-	- seepage via pipe lifting hole	3.7					
Swetion Image: Swetion Recommended Works Free commended Works Free commended Works Free commended Works Free commended Works n_{77} n_{67}	clean and repair with epoxy cement	-	- minor seepage via pipe joint	6.9	8	900	A18	A19	
SectionTerm <th r<="" td=""><td>clean and repair with epoxy coment</td><td>x :</td><td>- blocked pipe leaking</td><td>50.0</td><td></td><td></td><td></td><td></td></th>	<td>clean and repair with epoxy coment</td> <td>x :</td> <td>- blocked pipe leaking</td> <td>50.0</td> <td></td> <td></td> <td></td> <td></td>	clean and repair with epoxy coment	x :	- blocked pipe leaking	50.0				
Section To Interplay of Defect Recommended Works From To To Recommended Works Interplay of Defect Recommended Works $A27$ $A28$ 1200 $62.$ 5.3 - circumferential crock at top of pipe and aggragate exposed L monitor the situation $A28$ $A29$ 1050 61 51.4 - point invert sightly rough L monitor the situation $A28$ $A29$ 1050 61 51.4 - ap pipe intrudies 400 mm L ponoritor the situation $A28$ $A29$ 1050 610 pupe routate sightly rough L ponoritor the situation $A28$ $A29$ 1050 610 sign of rate on pipe well (seepage 7) L ponoritor the situation $A21$ $A25$ $A26$ 1350 34 $-$ no major problems, so $0X$ M clean pit $A25$ $A24$ 1650 592 $-$ no major problems, so $0X$ L lean of rapoir with gooy cament $A20$ $A20$ 592	clean and repair with enous cement	r 3	 break at top of nine seenage 	404	ç	900	774	24	
Image: Section of DefectRecommended Works Tom T_0	monitor the situation	E -	 indication in the second second	zo o	50	900	A99	A91	
Image: Section of DefectRecommended WorksFromToToImage: Section of DefectImage: Section of DefectImage: Section of DefectImage: Section of Section of DefectRecommended Works $I27$ $I28$ $I200$ $S6.2$ $S.3$ $-$ circumferential crock at top of pipe and aggragate exposedImage: Ministry Section of Test Sec	clean pipe	×	- sand & coarse aggregate on invert	0.0 - 50.0					
Sector To Image: Former former for the sector former for the sector former for the sector former former for the sector former former for the sector former	clean pipe	×	– coarse aggregate & debris on invert	0.0 - 8.0	c	006	2	neo	
Becommended Works Recommended Works From To To Second Works Recommended Works $ran To Second Works L Description of Defect L Recommended Works ran Ta Second Works L monitor the situation L monitor the situation rand Rand Second Pipe General Conduit at top of pipe and aggregate exposed L monitor the situation rand Rand Second Pipe Second Pipe and aggregate exposed L monitor the situation rand Rand Second Pipe Second Pipe and second around ag. Pipe intrudes 400 mm L monitor the situation rand Rand Second Pipe Second Pipe will (seepage ?) L monitor the situation L monitor the situation rand Rand Second Pipe Second Pipe will (seepage ?) L monitor the situation L monitor the situation rand Rand Second Pipe Second Pipe Will (seepage ?) L monitor the situation L $	clean pipe	м	- clear debris	0.5	8	006	154	A20	
Image: Set to the set of the s	clean and repair with epoxy cement		 damage in Pit A20 (exposed reinforcement) 						
Image: Section of Defect Recommended Works From To To Te Description of Defect It Recommended Works $A27$ $A28$ 1200 56.2 5.3 - circumferential crack at top of pipe ond aggregate exposed M Innifor the situation $A28$ $A29$ 1050 61 51.4 - sign of rust on pipe wall (seepage ?) L monifor the situation $A28$ $A29$ 1050 61 51.4 - sign of rust on pipe wall (seepage ?) L monifor the situation $A28$ $A29$ 1050 61 51.4 - sign of rust on pipe wall (seepage ?) L monifor the situation $A29$ $A30$ 1050 60.0 - some debris in pit M trim og. Pipe and seal around og. Pipe and seal around og. Pipe and seal around og. Pipe $A30$ $A31$ 900 17 0.6 - debris in pite M clean pit $A27$ $A26$ $A32$ 900 30 T - no major problems. so $0K$ M cl	clean and repair with epoxy cement	z :	 poor @100mm connection, reinforcement exposed 	11.0	34	900	A20	A19	
Image: Section of Defect Recommended Works From To To To Recommended Works Recommended Works $ran To Solution Solution of Defect L monitor the situation Recommended Works A27 A28 1200 Sol 27.9 - Inle in conduit at top of pipe and aggregate exposed M Idean and repair with epoxy cement A28 A29 1050 6.1 51.4 - sign of rust on pipe wall (seepage ?) L monitor the situation A28 A29 1050 6.1 51.4 - sign of rust on pipe wall (seepage ?) L monitor the situation A28 A29 1050 6.0 - some debris in pit M trim og. Pipe and seal around og. Pipe and seal around og. Pipe and seal around og. Pipe A30 A31 900 17 0.6 - some debris in pit M clean pit A27 A32 900 30 V_1 - debris d incoming 0375mm (Pit A31) M clean pit A27 A26 $	creat price	. ,	- shorten universe in pisto pinto pi	15 240	US BU	000	724	ne o	
Image: Section of Defect Recommended Works From To To Section of Defect L Recommended Works $ran To So So So Convertient crock at top of pipe ond aggregate exposed L monifor the situation A28 A29 1050 61 51.4 – sign of ration pipe woll (seepage ?) L monifor the situation A28 A29 1050 61 51.4 – sign of ration pipe woll (seepage ?) L monifor the situation A28 A29 1050 61 52.6 – sign of ration pipe woll (seepage ?) L monifor the situation A29 A30 60 52.6 – sign of ration pipe woll (seepage ?) L monifor the situation A30 A31 900 17 60.0 – some debris in pite M clean pite M clean pite A31 900 30 V 0.0 – a monifor problems, so OK M clean pit A27 A26 1350 $	n lean bit	-	- no major provising, so on small amount of debris in pit pipe OK	59.2	59	1650	A24	A25	
Image: Section of DefectRecommended WorksFromToToSection of DefectLMonitor the situation λT λR 1200 56.2 5.3 - circumferential crack at top of pipe and aggregate exposedLmonitor the situation λR 1200 56.2 27.9 - hole in conduit at top of pipe and aggregate exposedMclean and repair with epoxy cement λR 1050 61 51.4 - sign of rust on pipe wall (seepage ?)Lmonitor the situation λR 1050 60 19.4 - sign of rust on pipe wall (seepage ?)Lmonitor the situation λR 1050 60 19.4 - sign of rust on pipe wall (seepage ?)Lmonitor the situation λR 1050 60 19.4 - sign of rust on pipe wall (seepage ?)Lmonitor the situation λR 1050 60 19.4 - sign of rust on pipe wall (seepage ?)Lmonitor the situation λR 1050 60 19.4 - some debris in pitMtrim og. Pipe and seal around og. Pipe λR 1050 17 0.6 - some debris in pitMclean pit λR 30 17 17.8 - debris in pipeMclean pipe λR 400 300 30 17 17.8 - debris in pipeM λR 400 300 30 17.9 10.6 - debris in pipeM λR 400 300 300		1	- no major problems, so OK		<u>n</u> 4	1500	425 A26	A26	
Bestimultation Bescription of Defect Recommended Works From To To To To Recommended Works Feature Recommended Works From To To Set S.3 - circumferential crack at top of pipe Description of Defect L monitor the situation A27 A28 1200 S6.2 S.3 - circumferential crack at top of pipe ond aggregate exposed L monitor the situation A28 A29 1050 61 51.4 - sign of rust on pipe wall (seepage ?) L monitor the situation A28 A30 1050 60 19.4 - ag. pipe intrudes 400 mm L pony cement render pit invert A30 1050 60 52.6 - sign of rust on pipe wall (seepage ?) L monitor the situation A30 1050 60 52.6 - sign of rust on pipe wall (seepage ?) L monitor the situation A30 900 17 0.6 - debris in pit M clean pit monitor the situation			- no major problems, so UK		: 20	900	AS2	AJ	
Becommended Works Recommended Works From To To Second Works Recommended Works From To Second Works Second Works L Monitor the situation Recommended Works $\Lambda 27$ $\Lambda 28$ 1200 56.2 5.3 - circurferential crack at top of pipe ond aggregate exposed L monitor the situation $\Lambda 28$ $\Lambda 29$ 1050 61 51.4 - sign of rust on pipe woll (seepage ?) L monitor the situation $\Lambda 28$ $\Lambda 29$ 1050 60 19.4 - sign of rust on pipe woll (seepage ?) L monitor the situation $\Lambda 29$ $\Lambda 30$ 1050 60 19.4 - sign of rust on pipe woll (seepage ?) L monitor the situation $\Lambda 30$ 431 900 17 0.6 - some debris in pite M clean pite M clean pite $\Lambda 30$ 900 17 0.6 - debris in pipe M clean pipe M clean pipe	clean pit	×	- debris at incoming Ø375mm (Pit A31)	17.8	5	2	120		
Beside in the second works Recommended Works From To To Recommended Works Recommended Works $randow randow rando$	clean pipe	: 2	- debris in pipe	0.6	17	900	A31	A30	
Becommended Works Recommended Works From To To Second Works Recommended Works $randow Carrier 1200 56.2 5.3 - circumferential crack at top of pipe and aggregate exposed L monitor the situation A28 A29 1050 61 51.4 - sign of rust on pipe wall (seepage ?) L monitor the situation A28 A29 1050 61 51.4 - sign of rust on pipe wall (seepage ?) L monitor the situation A28 A29 1050 60 19.4 - og. pipe intrudes 400 mm L monitor the situation A29 1050 60 52.6 - sign of rust on pipe wall (seepage ?) L monitor the situation A29 1050 60 52.6 - sign of rust on pipe wall (seepage ?) L monitor the situation $	clean pit	×	- some debris in pit	60.0					
Section To Recommended Works From To To Convertient of the state of the	monitor the situation	-	- sign of rust on pipe wall (seepage ?)	52.6	60	1050	A30	A29	
Section Recommended Works From To Action of the structure of the	trim ag. Pipe and seal around ag. Pipe	< r	- ag. pipe intrudes 400 mm	19.4					
Section To Description of Defect Recommended Works From To - - - A28 1200 56.2 5.3 - circumferential crack at top of pipe and aggregate exposed L monitor the situation A28 1200 56.2 27.9 - hole in conduit at top of pipe and aggregate exposed M clean and repoir with epoxy cement	enovy cement render oit invert		 sign of rust on pipe wait (seepage :) 		đ	000	K7W	M20	
Section To Description of Defect Recommended Works From To	clean and repair with epoxy cement	- <	- hole in conduit at top of pipe and aggregate exposed	27.9	2	1050	A20	ASB	
Section Description of Defect Recommended Works	monitor the situation	: -	- circumferential crack at top of pipe	5.3	56.2	1200	A28	A27	
Section	Recommended Works		Description of Defect				To	From	
							tion	Sec	

COMMENTS
1.1
LINE
8

tion						
То				pescription of perect		
B01	1350	20	0 - 20	 pipe appears structurally OK, but water level in pipe high in pipe due to blocked downstream pipe 	т	unblock downstream pipe
B03	1050	υ	2.8	- infiltration	×	clean and seal pipe
			28.4	- fine roots at pipe joint	т	clean pipe joints and mortar with epoxy cement
B04	1050	76	39.5	- mass roots at pipe joint	т	clean pipe joints and mortar with epoxy cement

~ ~	ection						
From					Description of Defect		Recommended Works
B02	B01	1350	20	0 - 20	 pipe appears structurally OK, but water level in pipe high in pipe due to blocked downstream pipe 	т	unblock downstream pipe
B02	B03	1050	3	2.8	- infiltration	м	clean and seal pipe
				28.4	- fine roots at pipe joint	н	clean pipe joints and mortar with epoxy cement
B03	B04	1050	76	39.5	- mass roots at pipe joint	I	clean pipe joints and mortar with epoxy cement
				40.0	 debris caught in mass roots 	I	remove debris
COMME	NTS - L	INE C					
ŝ	oction						
From	То				Description of Defect		recommended works
C06	C07	1200	74		– no major problems, so OK		
C07	COB	1200	83	64 & 74	 infiltration via pipe lifting hole 	I	seal pipe lifting hole with epoxy mortar
				69.5 & 70.8	— cracked pipe — significant seepage	м	clean pipe cracks and mortar with epoxy cement
C06	C05	1200	91	76.9	 differential settlement & crcked pipe at invert 	z	clean pipe cracks and mortar with epoxy cement
				90.8	 defective ag pipe connection 	-	trim intruding pipe & seal around intruding pipe
C05	C03	1350	60	58.9	 defective small pipe connection 	-	trim intruding pipe & seal around intruding pipe
C03	C02	1350	49		- no major problems, so OK	ı	
					- intruding pipes at CH34.2, CH105.1, CH134.3 and CH171.0	-	trim intruding pipes & seal around intruding pipes
				34.4	- seepage through pipe	м	clean seepage area and seal with epoxy cement
C02	C01	1350	171	34.6	- spalled concrete	ĸ	clean spalled area and repair with epoxy cement
				155.5	 pipe damaged at invert, concrete chipped 	м	clean damaged area and repair with epoxy cement
				160.0	– open pipe joint – seepage via joint	×	clean pipe joint and seal with epoxy cement
				17.5 - 26.1	 leaking pipe lifting holes - significant infiltration drippers 	×	clean pipe lifting holes and seal with epoxy cement
3	011	1 750	107	26.1	– intruding 150 mm pipe, by 20 mm	-	clean around pipe and seal with epoxy cement
5		1.000	10,	35.0	– seepage via pipe joint	x	clean pipe joint and seal with epoxy cement
				73.6	 leaking pipe lifting holes 	-	clean pipe lifting holes and seal with epoxy cement
AOS	-			-			

Sec	tion:						
From	То				nescription of netect		
D06	D07	1050	87		– no major problems, so OK	1	
D07	D08	900	68	50.0 - 57.2	- four leaking pipe joints	F	clean pipe joints and seal with epoxy cement
nna	009	900	44	0.3	– minor circumferential crack	-	clean crack and seal with epoxy cement
000	003	900	1	12.0	- open pipe joint	ŗ	clean pipe joint and seal with epoxy cement
D06	D05	1050	24	22.7	 minor circumferential crack 	-	clean crack and seal with epoxy cement
D05	D04	1050	19		— no major problems, so OK	I	
D04	DO3	1050	58	35.6	- suspect pipe joint	-	monitor the situation
D03	D02	1050	39	3.9 - 31	- suspect pipe joints at Ch 3.9, Ch 28.7 and Ch 31	-	monitor the situation
				3.5	 infiltration at pipe joint 	r	clean pipe joint and seal with epoxy cement
D02	D01	1200	30	11.0	– large open pipe joint	т	clean pipe joint and seal with epoxy cement
				17.0	 leaking pipe lifting holes 	-	clean pipe lifting holes and seal with epoxy cement
D01	D01A	1200	20	7.3 - 20.3	 leaking pipe lifting holes 	-	clean pipe lifting holes and seal with epoxy cement
DO1A	A03	825	1200		— no major problems, so OK	ı	

8































