



**Photo 1:** Hylton Moore Park, showing recreation areas and car park facilities. (W01)



**Photo 2:** Boat ramp and jetty facilities at Erina Creek, looking upstream (north east). (W41, W107)



**Photo 3:** Gosford foreshore, looking east. (R14)



**Photo 4:** Stormwater traps along Gosford foreshore. (W27)



**Photo 5:** Boat ramp next to Iguana Joe's, Gosford. (P48, R31)



**Photo 6:** Gosford Public Wharf. (P48, R31)



**Photo 7:** Looking north along Ettalong Beach. The Ettalong Mantra Hotel and recreational users of Ettalong Beach are evident in the background. (W28, W97)



**Photo 8:** Ferry from Palm Beach to Wagstaffe/Ettalong. (R23, R34)



**Photo 9:** Boat ramp at Ettalong beach (mid tide). (P48, R31)



**Photo 10:** Boulders along Ettalong Beach (looking north). (W29)



**Photo 11:** Tree vandalism sign along the Ettalong foreshore. (C05)



**Photo 12:** Looking south along Ettalong foreshore – seawall with adjacent recreational area. Lack of beach



access points along this stretch. (W112)



**Photo 13:** Informal vessel ramp along Ettalong foreshore. (P48, R31, C14)

**Photo 14:** Informal boat ramp amidst numerous private jetties, at Woy Woy Bay. (P48, R31, C14)



**Photo 15:** Looking east towards Correa Bay, just downstream of Woy Woy Creek. (W04, W21)

**Photo 16:** Amenities located at Correa Bay Reserve. (W78)



**Photo 17:** Public baths along the Woy Woy foreshore - visually poor water quality. (W108)

**Photo 18:** Woy Woy jetty where ferry to Davistown, Saratoga and Empire Bay departs. (P48, R31)





**Photo 19:** Jetty at Lions Park (at end of North Berge Rd, Woy Woy) showing use of fishing nets. (P48, R31)



**Photo 20:** Fish cleaning facilities at Lions Park. (P48, R31)



**Photo 21:** Lions Park boat ramp. (P48, W80, R31)



**Photo 22:** Informal boat ramp at Koolewong Foreshore Reserve. (C14)



**Photo 23:** Erosion and rock armour along the Koolewong Foreshore. (W69)



**Photo 24:** Informal dinghy storage along Masons Parade, Point Frederick (looking south). (W77, W86)





**Photo 25:** Recreational use of beach north of Gosford Sailing Club. (W106)



**Photo 26:** Point Frederick seawall looking north. (W69)



**Photo 27:** Rocky point foreshore. (W104)



**Photo 28:** Yattalunga tidal pool showing depth at high tide. (W103).



**Photo 29:** Looking north along Mundoora Avenue, Yattalunga. (W38,W63,W10)



**Photo 30:** Centennial Avenue boat ramp at high tide. (W50, P48, R31)





**Photo 31:** Looking south along foreshore near Lintern Street, Davistown. (W48)



**Photo 32:** Looking east along Illoura Reserve foreshore. (W56)



**Photo 33:** Looking south from Carrak Road towards Kincumber Reserve. (C06)



**Photo 34:** RSL Creek culvert into Hardys Bay. (W23)



**Photo 35:** Foreshore erosion adjacent to Araluen Drive, Hardys Bay. (W39)



**Photo 36:** Empire Bay Wetland. (W71)





**Photo 37:** Oyster leases in Lintern Channel, near Davistown. (W100)



**Photo 38:** St Huberts Island, looking west. (W35)



**Photo 39:** Informal sea wall (R13)



**Photo 40:** Sedimentation in Hardys Bay. (W24, W120)



**Photo 41:** The Entrance to Brisbane Water, looking south west. (W18)



**Photo 42:** Brisbane Water Drive causeway adjacent to railway line (looking west). (W11, W12, R35)