
Monday, 14 January 2008 STORAGES						
Storage	Capacity Full [MI]	Volume in Storage [MI]	Percent Full [%]	Storage Change over last Week		
Mangrove Dam	190000	37,195	19.6	Down 16 ML		
Mardi Dam	7400	7,249	98.0	Down 89 ML		
Mooney Dam	4600	4,600	100.0	Unchanged		
Total	202000	49,044	24.3	Down 105 ML		

Total stored water volume is the same as a month ago. This day last year the volume stored as a percentage of total capacity was 10.8% lower. Hunter Water Corporation supplied 0 ML last week keeping this years supply at 0 ML. Gosford/Wyong supplied 0 ML to Hunter Water last week keeping this years supply at 0 ML. Groundwater Bores supplied 3.2 ML last week increasing this years supply to 5.7 ML.

## WATER USAGE & RAINFALL

Period	Water Usage [MI]	Rainfall [mm]					
		Somersby WTP	Mardi WTP	Mangrove Dam			
Week to date	495	4	4	12			
Previous week	480	8	10	14			
Current week last year	499	0	0	3			
This year to date	975	12	14	27			
Same period last year	981	21	12	7			
Week to date consumption was 495 ML, 0.8% less than the same week last year and 3.1% more than the previous week. Consumption this year to date is 975 ML, 0.6% less than the same period last year.							

Level 4 Water Consumption Target for the week ending Monday, 21 January 2008 is 475 ML



1 Black LineWyong Shire's normal demand when no restrictions are in place.2 Blue line8% reduction (based on the 'black line') over the entire year.3 Green Line16 % reduction (based on the 'black line') over the entire year.4 Pink Line24% reduction (based on the 'black line') over the entire year.5 Orange Line32% reduction (based on the 'black line') over the entire year.6 Blue barsRainfall at Somersby in mm/day.7 Red lineWyong Shire's average daily demand.

BLUE HAVEN SAN REMO C3 CATCHMENT C6 CATCHMENT BIRDWOOD DVE LIAMENA AVE Sewage Sewage Pumping Station Pumping Station C3 C6 C6 Pumping Station C3 Pumping Main **C3 Inter Connection Pipe Work** C6 Pumping Main C3 Pumping Main Inter Connection Pipe Work Stop Valves SPRING CREEK CHARMHAVEN SEWAGE TREATMENT WORKS HIAWATHA RD CHARMHAVEN

C3 and C6 Inter Connecting Sewer Lines